

TruVision IP TVP-11/31 Series Firmware V5.1.d Release Notes

P/N 1073028-EN • REV C - EMEA only • ISS 17JUN16

Introduction

This is the TruVision IP TVP-11/31 Series Firmware V5.1.d Release Notes with additional information not covered in the user manual. For the latest information on the TruVision IP PTZ camera, please visit:

EMEA: www.utcssecurityproducts.eu

Supported camera list

Note: You cannot downgrade the firmware from v5.1.d to v5.1.a. If the PTZ from the factory was loaded with v5.1.a, it can be upgraded to v5.1.d.

IP PTZ camera:

- TVP-1101 (1.3MPX wall-mount, PAL)
- TVP-3101 (1.3MPX wall-mount, NTSC)
- TVP-1102 (1.3MPX surface, PAL)
- TVP-3102 (1.3MPX surface, NTSC)
- TVP-1103 (1.3MPX flush, PAL)
- TVP-3103 (1.3MPX flush, NTSC)
- TVP-1104 (2MPX wall-mount, PAL)
- TVP-3104 (2MPX wall-mount, NTSC)
- TVP-1105 (2MPX surface, PAL)
- TVP-3105 (2MPX surface, NTSC)
- TVP-1106 (2MPX flush, PAL)
- TVP-3106 (2MPX flush, NTSC)
- TVP-1107 (2 MPX wall-mount, PAL)

- TVP-3107 (2 MPX wall-mount, NTSC)
- TVP-1122 (2 MPX wall-mount, IR, PAL)
- TVP-3122 (2 MPX wall-mount, IR, NTSC)

Improvements with Firmware V5.1.d

1. Added **QuickTime** live view option.

Note: To use QuickTime, the players need to be pre-installed.
2. Added **Firmware Directory** to the firmware upgraded option.
3. Added **Third Stream** option to the video stream type.
4. Improved audio features and added setting options to the browser.
 - a) Added **MP2L2** audio codec to audio encoding option.
 - b) Added **Audio Bit Rate** setting option.
 - c) Added **Audio Input** options to select *Line_in* or *Mic_in* device.
 - d) Added **Input Volume** adjustment to audio settings.
 - e) Added **Environmental Noise Filter** feature with *On/Off* options.
5. Improved *PTZ Configuration* settings to the browser.
 - a) Added **Max.Tilt Angle** setting option.
 - b) Added **Zoom Speed** setting option.
 - c) Added multiple **Min. Focus Distance** options: 10 cm, 50 cm, 1 m, 1.5 m, 3 m, 6 m, 10 m, and 20 m.
6. Added **Slow Shutter** settings with *On/Off* and *Shutter level* options.
7. Added **HLC** setting option for highlight compensation.
8. Added **Defog** setting option for use in foggy environments.
9. Added **EIS** setting option for electronic image stabilizing feature.
10. Added **Audio Exception Detection** feature and configuration to the browser UI.
11. Added **Storage Quota** feature to the browser UI. The storage capacity of a snapshot and recording can be user-defined.
12. Support extended **Lenel CGI command set** for integrating with UTC Lenel systems.
 - a) Added capture mode setting CGI command.
 - b) Added *GOV* setting command.
 - c) Added *PTZ Position* setting command.
13. Changed default capture mode from Off to 1920*1080 (2 MPX cameras) /1280* 960 (1.3 MPX cameras).

Issues resolved

1. Fixed BLC configuration failure issue.
2. Fixed the audio type configuration failure issue.
3. Resolved registering to ezDDNS server time out issue by increasing the delay time.

Contacting support

For help installing, operating, maintaining, and troubleshooting this product, refer to this document and any other documentation provided. If you still have questions, contact us during business hours (Monday through Friday, excluding holidays).

Note: Please be ready at the equipment before calling.

Table 1: Technical support

North America

T +1 855.286.8889

E techsupport@interlogix.com

W www.interlogix.com/customer-support

Europe, Middle East, and Africa

W Select *Contact Us* at www.utcssecurityproducts.eu

Australia

E security.tech.support@interlogix.com.au
